Target Property: 311 SOUTH EUCALYPTUS STREET JOB: TEAM 4

EL PASO, TX 79905

US BROWNFIELDS

EDR ID: 1016351498 DIST/DIR: 0.307 NW ELEVATION: 3706 MAP ID: 31

NAME: 1830 TEXAS AVENUE Rev: 02/23/2022

ADDRESS: 1830 TEXAS AVENUE ID/Status: Cleanup Completion Date: -

EL PASO, TX 79901 ID/Status: ACRES property ID: 12484

SOURCE: US Environmental Protection Agency

US BROWNFIELDS:

Name: 1830 TEXAS AVENUE Address: 1830 TEXAS AVENUE City,State,Zip: EL PASO, TX 79901 Recipient Name: El Paso, City of

Grant Type: Assessment

Property Number: -

Parcel size: -

Latitude: 31.769934 Longitude: -106.469617

HCM Label: -Map Scale: -Point of Reference: -Highlights: -

Datum: -Acres Prope

Acres Property ID: 12484 IC Data Access: -

Start Date: -

Redev Completition Date: - Completed Date: -

Acres Cleaned Up: Cleanup Funding: Cleanup Funding Source: Assessment Funding: Assessment Funding: Redevelopment Funding: Redev. Funding Source: Redev. Funding Entity Name: Redevelopment Start Date: Assessment Funding Entity: Cleanup Funding Entity: -

Grant Type: -

Accomplishment Type: Phase I Environmental Assessment

Accomplishment Count: N

Cooperative Agreement Number: 98686001

Start Date: 9/30/2004 Ownership Entity: -

Completion Date: 9/30/2004

Current Owner: Did Owner Change: Cleanup Required: Y
Video Available: Photo Available: -

Institutional Controls Required: -

- Continued on next page -

Target Property: 311 SOUTH EUCALYPTUS STREET JOB: TEAM 4

EL PASO, TX 79905

US BROWNFIELDS

EDR ID: 1016351498 DIST/DIR: 0.307 NW ELEVATION: 3706 MAP ID: 31

NAME: 1830 TEXAS AVENUE Rev: 02/23/2022

ADDRESS: 1830 TEXAS AVENUE ID/Status: Cleanup Completion Date: ID/Status: ACRES property ID: 12484

EL PASO, TX 79901

SOURCE: US Environmental Protection Agency

IC Category Proprietary Controls: -

IC Cat. Info. Devices: - IC Cat. Gov. Controls: -

IC Cat. Enforcement Permit Tools: -

IC in place date: - IC in place: U

State/tribal program date: -State/tribal program ID: -State/tribal NFA date: -

Air cleaned: -Asbestos found: -Asbestos cleaned: -

Controled substance found: -Controled substance cleaned: -Drinking water affected: -Drinking water cleaned: -

Groundwater affected: -Groundwater cleaned: -Lead contaminant found: -

Lead cleaned up: -No media affected: -Unknown media affected: -

Other cleaned up: -

Other metals found: Other metals cleaned: Other contaminants found: -

Other contams found description: -

PAHs found: PAHs cleaned up: PCBs found: PCBs cleaned up: Petro products found: Petro products cleaned: -

Sediments found: Sediments cleaned: Soil affected: Soil cleaned up: Surface water cleaned: -

VOCs found: -VOCs cleaned: -

Cleanup other description: -Num. of cleanup and re-dev. jobs: -Past use greenspace acreage: -Past use residential acreage: -

Surface Water: -

- Continued on next page -

Target Property: 311 SOUTH EUCALYPTUS STREET JOB: TEAM 4

EL PASO, TX 79905

US BROWNFIELDS

EDR ID: 1016351498 DIST/DIR: 0.307 NW ELEVATION: 3706 MAP ID: 31

NAME: 1830 TEXAS AVENUE Rev: 02/23/2022

ADDRESS: 1830 TEXAS AVENUE ID/Status: Cleanup Completion Date: ID/Status: ACRES property ID: 12484

EL PASO, TX 79901

SOURCE: US Environmental Protection Agency

Past use commercial acreage: -

Past use industrial acreage: -

Future use greenspace acreage: -

Future use residential acreage: -

Future use commercial acreage: -

Future use industrial acreage: -

Superfund Fed. landowner flag: -

Arsenic cleaned up: -

Cadmium cleaned up: -

Chromium cleaned up: -

Copper cleaned up: -

Iron cleaned up: - mercury cleaned up: -

Nickel Cleaned Up: -

No clean up: -

Pesticides cleaned up: -

Selenium cleaned up: -

SVOCs cleaned up: -

Unknown clean up: -

Arsenic contaminant found: -

Cadmium contaminant found: -

Chromium contaminant found: -

Copper contaminant found: -

Iron contaminant found: -

Mercury contaminant found: -

Nickel contaminant found: -

No contaminant found: -

Pesticides contaminant found: -

Selenium contaminant found: -

SVOCs contaminant found: -

Unknown contaminant found: -

Future Use: Multistory -

Media affected Bluiding Material: -

Media affected indoor air: -

Building material media cleaned up: -

Indoor air media cleaned up: -

Unknown media cleaned up: -

Past Use: Multistory -

Property Description: -

Below Poverty Number: 2833

Below Poverty Percent: 68.56

Meidan Income: 1276

Meidan Income Number: 3927 Meidan Income Percent: 95.04 Vacant Housing Number: 191

- Continued on next page -

JOB:

TEAM 4

Target Property: 311 SOUTH EUCALYPTUS STREET

EL PASO, TX 79905

US BROWNFIELDS

EDR ID: 1016351498 **DIST/DIR**: 0.307 NW **ELEVATION**: 3706 **MAP ID**: 31

NAME: 1830 TEXAS AVENUE Rev: 02/23/2022

ADDRESS: 1830 TEXAS AVENUE

ID/Status: Cleanup Completion Date: ID/Status: ACRES property ID: 12484

EL PASO, TX 79901 ID/Status: ACRES property ID: 12484

SOURCE: US Environmental Protection Agency

Vacant Housing Percent: 13.07 Unemployed Number: 182 Unemployed Percent: 4.4